
Test Report Number: GZHH00285272

Applicant: DONGGUAN TAITE MATERIAL CO LTD
ROOM 710, NO. 14, EAST OF,HOUJIE TOWN
DONGGUAN

Date: Jun 21, 2018

Attn: Amy Wu

Sample Description:
One (1) submitted sample said to be **skyjump high performance special leather**
Date Sample Received : May 01, 2018



****

Tests conducted:
As requested by the applicant, refer to attached page(s) for details.
****

Conclusion:
Based upon the test results reported, the sample meets the requirement of Schedule 4 Part I of the Furniture and Furnishings (Fire) (Safety) Regulations 1988 (as amended).
Based upon the test results reported, the sample meets the requirement of Schedule 5 Part I of the Furniture and Furnishings (Fire) (Safety) Regulations 1988 (as amended).
****

Authorized by:
For Intertek Testing Services Shenzhen Ltd.
Guangzhou Branch, Hardlines

Ben N.L. Lin
General Manager

Intertek Testing Services Shenzhen Limited, Guangzhou Branch
深圳天祥质量技术服务有限公司广州分公司
#111 TCL Cultural Industry Park, Guangpu-west Road, Science City, High and New Technology Industrial Development Zone, Guangzhou. / E501, No.7-2, Caipin Road, Guangzhou Science City, GETDD Guangzhou.
广州高新技术开发区科学城光谱西路 69 号 TCL 文化产业园汇创空间 111/广州经济技术开发区科学城彩频路 7 号之二 E501(510663)
Tel +8620 8213 9688
Fax +8620 3205 3537
intertek.com.cn
intertek.com

Test Report Number: GZHH00285272

Tests Conducted

1 Flammability Test (BS 5852:Part 1:1979, Cigarette Test):

The Test, Specified In Schedule 4 Part I Of The Furniture And Furnishing (Fire) (Safety) Regulations 1988 (As Amended In 1989, 1993 And 2010), Is Based On BS 5852 Part 1:1979 Using Ignition Source - Cigarette.

To Assess The Ignitability Of Visible Cover With Standard Filling Material Used In Upholstered Components When Subjected To A Smouldering Cigarette.

The Following Test Results Relate Only To The Ignitability Of The Combination Of Materials Under The Particular Conditions Of Test; They Are Not Intended As A Means Of Assessing The Full Potential Fire Hazard Of The Materials In Use.

Conditioning : 72 hours Indoor Ambient And At Least 16 hours Of 20±5°C, 50±20% Relative Humidity.
Testing Atmosphere : 15-30°C, 20-70% Relative Humidity
Flame Retardant Finishing Of Visible Cover : Yes
Soaking Condition : Clause 4.2-4.5 of BS 5651:1978 As Modified By The Furniture and Furnishings (Fire) (Satety) Regulations 1988, 30 minutes at 40°C, Line Dry.
Performance Requirement : Clause 9 Of BS 5852 Part 1:1979

Test Result:

Progressive Smoldering Failure	1st Test	Retest
(A) Evidence Of Progressive Smouldering In The Interior And/Or Cover During Combustion.	No	No
(B) Progressive Smouldering Of The Upholstery Components Is Observed At Any Time Within A Period Of One Hour Of The Placement Of The Cigarette;	No	No
(C) On Final Examination Progressive Smouldering Is Observed On The Assembly Dismantle And Examined It Internally.		No
Flaming Failure		
(A) Evidence Of Flaming In The Interior And/Or Cover During Combustion;	No	No
(B) Flaming Of The Upholstery Components Is Observed At Any Time Within A Period Of One Hour Of The Placement Of The Cigarette.	No	No

Fabric/ Standard Filling	Ignition Source	Time To Extinction After Placement Of Ignition Source			
		Flaming Ceased Time		Smoking Ceased Time	
		min	sec	min	sec
1	0	0	0	3*	44
Retest	0	0	0	4*	12

Remark : No = Was not observed
The fabric was tested with non fire-retardant polyurethane foam type b.
*= Failed to smoulder to cigarette complete length

Note : There was insufficient filling material to carry out the cigarette test out over the actual upholstery composite so as suggested by the guide to the furniture regulations the cover fabric was tested for cigarette resistance using standard polyurethane foam (non-modified) as this will give the furniture manufacturer a good indication of its likelihood to pass the cigarette test for the finished article.

****

Intertek Testing Services Shenzhen Limited, Guangzhou Branch
深圳天祥质量技术服务有限公司广州分公司
#111 TCL Cultural Industry Park, Guangpu-west Road, Science City, High and New Technology Industrial Development Zone, Guangzhou. / E501, No.7-2, Caipin Road, Guangzhou Science City, GETDD Guangzhou.
广州高新技术开发区科学城光谱西路 69 号 TCL 文化产业园汇创空间 111/广州经济技术开发区科学城彩频路 7 号之二 E501(510663)
Tel +8620 8213 9688
Fax +8620 3205 3537
intertek.com.cn
intertek.com

Test Report Number: GZHH00285272

Tests Conducted

2 Flammability Test (BS 5852 Part 1:1979, Match Test):

The test, specified in schedule 5 Part I of The Furniture and Furnishings (Fire) (Safety) Regulations 1988 (as amended in 1989,1993 and 2010), is based on BS 5852 part 1:1979 using ignition source 1 - match test for 20 seconds.

To assess the ignitability of visible cover with standard filling material used in upholstered components when subjected to ignition flame.

The following test results relate only to the ignitability of the combination of material under the particular conditions of test; they are not intended as a means of assessing the full potential fire hazard of the materials in use.

Conditioning : 72 hours indoor ambient and at least 16 hours of 20±5°C, 50±20% relative humidity.
Testing Atmosphere : 15-30°C, 20-70% relative humidity
Flame Retardant Finishing Of Visible Cover : Yes
Soaking Condition : Clause 4.2-4.5 of BS 5651:1978 As Modified By The Furniture and Furnishings (Fire) (Satety) Regulations 1988, 30 minutes at 40°C, Line Dry.
Performance Requirement : Clause 9 of BS 5852 part 1:1979

Test Result:

Progressive Smouldering Failure	1st Test	Retest
(A) Evidence of progressive smouldering in the interior and/or cover after 120 seconds of the removal of burner tube.	No	No
(B) On final examination progressive smouldering is observed on the assembly dismantle and examined it internally.		No
Flaming Failure		
(A) Evidence of flaming in the interior and/or cover after 120 seconds of the removal of burner tube.	No	No

Fabric	Ignition Source	Time To Extinction After Removal Of Burner			
		Flaming Ceased Time		Smoking Ceased Time	
		Min	Sec	Min	Sec
1	1	0	1	0	15
Retest	1	0	1	0	16

Remark : No = Was not observed

****

End of report

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. This report shall not be reproduced unless with prior written approval from Intertek Testing Services Shenzhen Limited, Guangzhou Branch.

Intertek Testing Services Shenzhen Limited, Guangzhou Branch
深圳天祥质量技术服务有限公司广州分公司
#111 TCL Cultural Industry Park, Guangpu-west Road, Science City, High and New Technology Industrial Development Zone, Guangzhou. / E501, No.7-2, Caipin Road, Guangzhou Science City, GETDD Guangzhou.
广州高新技术开发区科学城光谱西路 69 号 TCL 文化产业园汇创空间 111/广州经济技术开发区科学城彩频路 7 号之二 E501(510663)
Tel +8620 8213 9688
Fax +8620 3205 3537
intertek.com.cn
intertek.com